

Fundamentals of Beginner Blacksmithing: Scrap Steel Anvil Fabrication and Introductory Tong Forging

Introduction to Scrap-Based Blacksmithing and Thermomechanical Processing

The practice of blacksmithing represents the fundamental manipulation of ferrous metals through localized thermal application and applied kinetic energy. For the beginning practitioner, the initial barrier to entry often lies in the procurement of high-mass tooling, specifically the anvil, and the specialized gripping implements required to handle incandescent steel safely. The historical and contemporary solution to this mechanical barrier is the intelligent repurposing of industrial scrap steel.

The structural integrity, metallurgical composition, and geometric configuration of heavy industrial scrap—such as decommissioned railroad track segments and discarded forklift tines—present ideal candidates for ad-hoc anvil fabrication. However, the successful transformation of these raw materials into highly functional forging equipment requires a rigorous understanding of metallurgical phase transformations, acoustic physics, and abrasive material removal techniques. Furthermore, the synthesis of the blacksmith's foundational skills culminates in the forging of their own tongs—a rite of passage that codifies the principles of isolating mass, directional drawing out, and mechanical fastening.

This comprehensive analysis details the metallurgical profiles of common high-mass scrap steels, the exact physical and mechanical steps required to fabricate a highly efficient starter anvil, the procedural sequence for forging a beginner's pair of tongs, and the critical occupational safety frameworks that govern the traditional and modern forge.

Part I: Metallurgical Characterization of Scavenged High-Mass Steels

The selection of scrap steel for an anvil cannot be arbitrary. An anvil must possess sufficient surface hardness to resist plastic deformation under repeated hammer strikes, while simultaneously maintaining immense internal toughness to prevent catastrophic brittle fracture. Two of the most ubiquitous and legally obtainable heavy scrap items are railroad tracks and forklift tines, both of which present distinct metallurgical profiles that must be understood prior to fabrication.

The Metallurgy of Railroad Rail Steel

A pervasive misconception in amateur blacksmithing circles is that railroad track is universally equivalent to simple AISI 1084 high-carbon steel¹. While the nominal carbon content may be

similar, railroad rail is a highly engineered, purpose-built material governed by strict international standards such as the American Railway Engineering and Maintenance-of-Way Association (AREMA), the European UIC900A, and the Chinese U71Mn¹. Modern rail steel is typically a high-carbon, high-manganese hypoeutectoid or eutectoid alloy. The typical chemical composition consists of 0.70% to 0.85% Carbon (C) and 0.70% to 1.20% Manganese (Mn), with highly controlled limits on impurities¹.

Element	Typical Range	Metallurgical Function in Rail Steel
Carbon (C)	0.50% –	Provides primary hardness and wear resistance; forms cementite in the pearlite matrix.
Manganese (Mn)	0.70% –	Lowers the eutectoid point, refines pearlite interlamellar spacing, and massively improves deep hardenability and impact toughness.
Silicon (Si)	0.10% –	Acts as a deoxidizer during smelting; provides solid-solution strengthening to the ferrite phase.
Phosphorus (P)	<	Strictly limited impurity; excess causes cold-shortness (brittleness at ambient temperatures).
Sulfur (S)	<	Strictly limited impurity; excess causes hot-shortness (cracking during high-temperature forging).

The high carbon content allows the rail head to resist the extreme contact stress of steel train

wheels, while the manganese ensures the steel maintains high impact toughness and fatigue resistance to withstand cyclic loading¹. Unlike many tool steels that rely on a heat-treated martensitic crystalline structure for hardness, standard railroad track derives its immense durability from a highly refined pearlitic microstructure¹. Pearlite is a two-phase, lamellar (layered) structure composed of alternating microscopic bands of ductile ferrite (alpha-iron)

and hard, brittle cementite (iron carbide, Fe_3C)⁵.

The defining mechanical characteristic of pearlitic rail steel is its exceptional capacity for in-service work hardening¹. As heavy train wheels—or a blacksmith's hammer—strike the surface, the localized plastic deformation causes the dislocation density within the crystalline lattice to increase exponentially. This strain-hardening phenomenon means that an older, used piece of railroad track will possess a significantly harder running surface than a brand-new, unladen segment, with field measurements showing surface hardness increasing from a baseline of 370 HV0.1 up to 550 HV0.1 simply through service wear⁶.

The Metallurgy of Forklift Tines (42CrMo4 / AISI 4140)

Forklift tines represent massive, homogenous blocks of high-grade alloy steel, engineered to withstand immense cantilevered loads without yielding or fracturing. The dominant alloy used globally for this application is AISI 4140, or its European structural equivalent, 42CrMo4 (Material Number 1.7225)⁸.

The designation 42CrMo4 is derived directly from the DIN EN 10027-1 nomenclature system¹⁰.

In this system, the "42" indicates an average carbon content of 0.42% (multiplied by a factor of 100 for naming purposes)¹². The "Cr" and "Mo" indicate the primary alloying elements of chromium and molybdenum¹². The "4" indicates a chromium content of approximately 1.0% (multiplied by a factor of 4)¹².

Property / Element	42CrMo4 (Forklift Tine)	C45 / 1045 (Medium Carbon Reference)
Carbon (C)	0.38% —	0.42% —
Chromium (Cr)	0.90% —	None
Molybdenum (Mo)	0.15% —	None
Yield Strength	≈ 600 —	≈
Tensile Strength	700 —	570 —

Typical Hardness	28 —	15 —
------------------	------	------

Unlike the pearlitic rail steel, 42CrMo4 is a quenched and tempered (Q+T) martensitic steel. It possesses superior tensile strength and a highly uniform hardness across deep cross-sections due to the immense hardenability provided by the chromium and molybdenum¹². When scavenging a forklift tire, the blacksmith is acquiring a block of steel that already possesses an ideal metallurgical state—tough, highly resistant to impact, and boasting a hardness of approximately 28 to 35 HRC (Hardness Rockwell C) depending on its tempering history¹². This balance of hardness and toughness makes it an ideal candidate for an anvil, as it will resist denting without the risk of brittle chipping along the edges.

Part II: The Physics of Forging and Anvil Efficiency

An anvil is not merely a passive, hard surface; it is an active mechanical participant in the forging process. The efficiency of a blacksmith's labor is entirely dictated by the anvil's ability to resist the kinetic energy of the hammer blow and reflect that energy back into the plastic deformation of the hot steel workpiece¹⁶.

The Mass Ratio and Kinetic Energy Transfer

The physics of manual forging are governed by the conservation of momentum and the

transfer of kinetic energy. The kinetic energy (E) delivered by the hammer is calculated using the standard formula:

$$E = \frac{1}{2}mv^2$$

Where m is the mass of the hammer and v is the velocity at the moment of impact¹⁷.

When the hammer strikes the hot workpiece resting on the anvil, the ideal outcome is for the kinetic energy to be absorbed entirely by the plastic yielding of the hot steel. However, if the anvil lacks sufficient mass, a significant portion of the kinetic energy will be lost to accelerating the anvil itself downward (due to the conservation of momentum) rather than moving the workpiece¹⁶. The anvil will absorb the blow and physically move, wasting the smith's effort.

To counteract this, empirical engineering standards dictate that the mass of the anvil must dwarf the mass of the hammer. A minimum anvil-to-hammer mass ratio of 20:1 is required for acceptable mechanical efficiency, while a ratio of 40:1 or greater is considered optimal for

professional forging¹⁸. Therefore, a blacksmith wielding a standard 1.5 kg (3.3 lb) forging

hammer requires an anvil mass of at least 30 kg (66 lbs), with 60 kg (132 lbs) being highly preferable to ensure a "dead blow" where energy is efficiently reflected²⁰.

Furthermore, it is not merely the total mass of the object that matters, but the mass located directly beneath the vertical vector of the hammer blow—referred to as the columnar mass²².

Orienting the Railroad Track Anvil

The most consequential decision a beginner must make when fabricating an anvil from a segment of railroad track is its spatial orientation: horizontal or vertical.

Horizontal Mounting (The Suboptimal Approach): Laying the track flat (with the head facing up and the wide flange bolted down to a bench) superficially mimics the shape of a traditional London-pattern anvil. However, this orientation is mechanically inferior for forging²³. A typical foot-long segment of rail mounted horizontally places only the thin vertical web of the track directly under the hammer. When struck, this web acts identically to a leaf spring; it flexes microscopically under the load²³. This elastic deformation absorbs the kinetic energy of the hammer, resulting in poor rebound, rapid physical fatigue for the smith, and highly inefficient metal movement²⁵. Additionally, the top of a heavily used rail is typically crowned (convex), which severely reduces the contact patch and causes hot steel to slip sideways under the hammer²⁵.

Vertical Mounting (The Optimal Approach): The vastly superior geometric configuration is to mount the rail segment vertically, standing it upright on its factory-cut transverse end²². While this provides a much smaller working face (roughly the cross-section of the rail head and web), it completely alters the mechanical dynamics. Vertical mounting aligns the entire mass of the steel segment directly under the hammer blow as a solid column²². A 40-centimeter vertical segment of heavy rail places an unbroken column of solid steel against the earth, completely eliminating web flex and maximizing the efficiency of energy transfer into the workpiece¹⁶. If the rail segment is sufficiently long, the smith can bury the lower half of the vertical column directly into the ground or a deep bucket filled with concrete. This not only provides immense stability but essentially couples the mass of the anvil to the mass of the earth, artificially increasing the effective mass ratio and providing exceptional rebound²³.

Part III: Mechanical Fabrication of the Scrap Anvil

To increase the utility of the repurposed steel, the raw block must undergo abrasive shaping. This involves the fabrication of a horn (if required) and the critical process of edge radiusing to prevent metallurgical failure of the tools forged upon it.

Abrasive Shaping and Horn Fabrication

If a horizontal track orientation is chosen despite its flaws (or if utilizing a massive block like a forklift tine), the smith may wish to fabricate a horn (bick) for drawing out material and turning tight scrolls. On a railroad track, this is achieved by cutting away the web and flange at one end, leaving an overhanging section of the rail head²².

This process relies on abrasive material removal utilizing a heavy-duty angle grinder (typically 180mm to 230mm) fitted with high-quality cutoff wheels²⁷. The procedure is as follows:

1. The steel is secured firmly. The optimal height is slightly below the pelvis, allowing the operator to look down upon the cutting line and brace their elbows against their torso for maximum stability²⁷.
2. A thin, highly visible scribe line is marked. The cut should be made adjacent to this line, rather than directly on it, to ensure dimensional accuracy²⁷.

3. The angle grinder is started and allowed to rest its weight against the cut; forced downward pressure is strictly avoided. Forcing the wheel drops its RPM, drastically increasing friction and the likelihood of a violent, dangerous kickback or catastrophic wheel shatter²⁷. The operator must "feel" the grinder; if it begins to jump or stutter, pressure must be immediately relieved²⁷.
4. By employing a continuous, rhythmic "sawing" motion, a straight cut can drop an 8mm thick slice from the rail in under ten minutes using a premium 2mm thick cutoff wheel²⁷.
5. Once the rough step is cut out, aggressive flap discs (36 to 60 grit) are used to grind the overhanging rail head into a smooth, tapered cone to serve as the horn²⁸.

Radiusing the Edges: Mitigating Stress Risers

Whether utilizing a forklift tine or a rail segment, the sharp 90-degree factory edges of the steel block must be addressed prior to forging²². If a piece of incandescent steel is hammered over a perfectly sharp 90-degree anvil edge, the anvil will forge a microscopic, sharp internal corner into the workpiece²⁹.

In metallurgy and mechanical engineering, a sharp internal corner acts as a severe stress riser—a geometrical focal point where applied forces are exponentially concentrated²⁹. As the smith continues to bend, draw, or twist the workpiece, the stresses concentrate aggressively at this sharp notch, leading to rapid crack propagation and eventual brittle fracture²⁹.

Furthermore, striking hot metal over a sharp edge can cause the outer layer of metal to fold over itself without welding, creating a dangerous internal shear plane known as a "cold shut"²⁹. To prevent the induction of stress risers and cold shuts, the smith must use a flap disc or dedicated grinding wheel to apply a smooth radius along the working edges of the anvil²⁹. Best practice involves creating variable radii along the length of the anvil: leaving a very tight radius ($1/16$ -inch) near the heel for crisp shouldering and precise ninety-degree bends, transitioning to a softer, more forgiving radius ($1/4$ -inch to $3/8$ -inch) toward the center of the anvil for aggressive drawing out and fullering operations³⁰.

Hardfacing and Surface Repair of Alloy Steels

If the surface of a salvaged 42CrMo4 forklift tine is deeply gouged, the smith may attempt to restore the face through welding. However, welding high-carbon or medium-carbon alloys like 42CrMo4 introduces severe risks of heat-affected zone (HAZ) cracking due to rapid localized martensite formation¹².

To successfully repair or hardface a 42CrMo4 anvil:

1. The entire steel block must be preheated uniformly to between $200^{\circ}C$ and $300^{\circ}C$ to slow the cooling rate of the weld pool and prevent brittle phase transformations in the HAZ¹².
2. A ductile "buttering" layer is highly recommended. This is typically applied using an E7018 low-hydrogen Shielded Metal Arc Welding (SMAW) electrode³⁵. This ductile layer acts as a mechanical shock absorber between the rigid base metal and the extreme hardness of

the final surface.

3. The final working face is then built up using specialized hardfacing electrodes, such as E DUR 600³⁸. When deposited over a properly prepared and preheated 42CrMo4 base, an E DUR 600 electrode will yield a highly wear-resistant surface approaching 55 to 59 HRC, providing an exceptional striking surface for the anvil³⁸.

Acoustic Dampening: The Impedance Mismatch Interface

When a hammer strikes an anvil, the kinetic energy not consumed by deforming the hot steel transfers directly into the elastic mass of the anvil body⁴². This energy excites the natural resonant frequencies of the steel, resulting in extreme, high-frequency acoustic vibrations—the characteristic deafening "ring" of an anvil⁴². This ringing is not only a severe occupational hazard capable of causing cumulative hearing loss, but it also represents mechanical inefficiency⁴². To silence the anvil, its mass must be mechanically coupled to the mass of the earth via an anvil stand (typically a massive hardwood log or a fabricated steel tripod)⁴². However, microscopic surface irregularities between the uneven bottom of the rough scrap steel and the top of the wooden stand prevent perfect mechanical coupling, allowing the steel to vibrate freely against the wood⁴².

The optimal modern solution is the application of a thick, continuous bed of 100% pure silicone caulk between the anvil and the stand⁴².

1. A heavy, continuous bead of silicone is applied across the top surface of the wooden log.
2. The anvil is carefully lowered into the wet silicone bed.
3. The anvil is aggressively bolted or strapped down with heavy steel bands or forged staples while the silicone cures under pressure⁴².

From an acoustical physics perspective, the cured silicone acts as a highly efficient elastomeric vibration dampener⁴². It fills every microscopic void, providing absolute, unbroken surface

contact. The silicone possesses an acoustic impedance ($Z = \rho c$, where ρ is the density of the material and c is the speed of sound within it) that differs vastly from both the high-density steel and the cellular structure of the wood⁴⁵.

When the high-frequency vibrational waves attempt to propagate from the steel into the elastomeric silicone, this severe acoustic impedance mismatch, coupled with the high internal damping coefficient of the polymer, absorbs and dissipates the acoustic energy as trace amounts of thermal energy⁴³. This perfectly attenuates the high-frequency ringing, transforming the ear-piercing scream of the steel into a dull, highly efficient thud⁴². Wrapping heavy iron chains tightly around the narrow waist of the anvil can further reduce transverse vibrations through simple frictional mass damping⁴².

Part IV: Foundational Forging Techniques: Fabricating Blacksmithing Tongs

With the combustion core (the forge) and the primary kinetic reflecting surface (the anvil) established, the blacksmith requires the mechanical means to safely manipulate incandescent

steel. Standard hardware tools or slip-joint pliers are dangerously inadequate; their short handles conduct heat rapidly to the user's hands, and their generalized jaws cannot securely lock onto heavy stock⁴⁷.

The forging of a pair of tongs is the ultimate pedagogical exercise for the beginner. It demands the synthesis and mastery of mass isolation, tapering, shouldering, hole punching, and riveting—forming the foundational grammar of the craft⁴⁸.

Typology of Tongs and Stock Selection

Tongs are categorized by their jaw geometry, which must precisely match the stock being held. Using incorrect tongs results in a loose, precarious grip, posing a severe safety hazard as a poorly held, glowing billet can easily be ejected at high velocity from a misplaced, off-center hammer blow⁴⁷.

Tong Type	Jaw Geometry	Intended Application
Flat Jaw	Flat, parallel inner surfaces.	Designed exclusively for holding flat bar stock securely.
Bolt Jaw	Curved or V-notched jaw that arches over a swollen center.	Grips square and round stock firmly, bypassing widened heads (like a bolt).
V-Bit	Deep V-shaped grooves running parallel to the jaw length.	Provides four points of contact for absolute security on square and round rod.
Wolf Jaw	Undulating, multi-toothed, self-adjusting profile.	Highly versatile for irregular shapes, but lacks the absolute locking security of dedicated V-bit tongs.

For the absolute beginner, flat jaw tongs are the most accessible to forge. The optimal starting material is two lengths of $1\frac{1}{2}$ -inch square or round mild steel bar stock, approximately 16 inches long, or alternatively, a pair of high-carbon railroad spikes⁴⁹. Mild steel is highly preferred for initial attempts due to its wide forging temperature range, lack of air-hardening properties, and ease of plastic deformation²⁹.

The Forging Sequence: The Rule of 90 Degrees

A pair of tongs consists of two identical halves that are mirrored during assembly. The architecture of each half consists of three distinct physical zones: the jaw (nib), the boss (the

central hinge plate), and the rein (the long handle). The transition between these zones is achieved through a technique known as "setting down," which systematically isolates the mass⁴⁸.

Step 1: The First Set-Down (Forming the Jaw)

1. The end of the bar is brought to a bright yellow forging heat (approximately $1100^{\circ}C$).
2. The bar is laid horizontally across the anvil face so that approximately 1.0 to 1.5 inches of the hot metal protrudes over the far edge of the anvil⁵⁰.
3. The smith strikes the metal with half-face hammer blows—striking so that half the hammer face hits the steel, and the other half passes harmlessly into the empty air beyond the anvil edge⁵¹.
4. This creates a distinct, sharp shoulder (the set-down), reducing the thickness of the protruding jaw section to approximately $1/4$ -inch thick while leaving the parent bar fully intact⁵⁰.

Step 2: The Second Set-Down (Forming the Boss)

This is the critical step that defines the functional geometry of the tongs.

1. The steel is pulled back toward the operator, resting on the near edge of the anvil.
2. The smith rotates the bar exactly 90 degrees counter-clockwise (if right-handed)⁵⁰. The newly formed jaw should now be pointing vertically up or down, hanging entirely off the near edge.
3. Leaving an untouched section of about 1 to 1.5 inches of full-thickness material to act as the boss, the smith performs a second half-face set down just behind this boss zone⁵⁰.
4. This step isolates the thick, square boss between the flattened jaw and the rest of the parent bar. Crucially, the transition from the jaw to the boss must be slightly radiused—striking a sharp internal corner here will create a severe stress riser, inevitably causing the tongs to snap at the hinge during heavy use³⁰.

Step 3: The Third Set-Down (Drawing the Reins)

1. The bar is rotated another 90 degrees counter-clockwise. The initial jaw is now pointing horizontally to the right (parallel to the anvil edge)⁵².
2. A third set-down is performed directly behind the boss. This defines the start of the rein⁵⁰.
3. The long remaining section of the bar is drawn out (tapered) over the horn or the radiused edge of the anvil. Drawing out over the radiused edge is highly efficient, as the curve acts as a continuous fuller, aggressively displacing metal linearly rather than flattening it outward⁵⁰. The reins should taper gradually from the thick boss down to a comfortable, springy thickness at the hand.

The entire sequence is then repeated identically on the second piece of steel⁵³. The "rule of 90 degrees" ensures that both halves possess the correct asymmetrical offset, allowing the jaws to align perfectly parallel when the flat bosses are laid against one another.

Punching and Riveting the Pivot

The two halves must be joined mechanically at the boss. While the hole for the rivet can technically be drilled with modern machinery, traditional hot punching is metallurgically superior.

1. The boss is heated to a bright yellow.
2. A tapered tool steel punch is driven through the exact center of the boss over the pritchel hole (the small round hole) of the anvil.
3. Punching, unlike drilling, does not sever the continuous grain flow of the steel; instead, it aggressively displaces and compresses the grain lines around the circumference of the hole, maintaining the structural integrity of the highly stressed hinge area⁴⁹. The thermal "suck-down" effect of the punch will naturally thin the boss slightly, which is why it must be left initially thick (at least $\frac{3}{8}$ -inch) during the set-down phase⁵¹.

To assemble the tongs:

1. A $\frac{1}{4}$ -inch or $\frac{3}{8}$ -inch mild steel rivet is inserted through the aligned holes of both cold halves⁴⁹.
2. The protruding tail of the rivet is heated to a localized red heat using an oxy-acetylene torch, or the entire boss assembly is heated carefully in the forge fire.
3. The rivet is backed by the solid anvil face, and the hot tail is peened over with aggressive hammer blows, swelling the shaft to completely fill the punched holes and mushrooming the head to lock the assembly⁵³.
4. Initially, the hot riveting process will cause the tongs to seize completely solid. To free the joint, the entire boss section is brought back to a dull red heat. The smith grips the cold reins and aggressively opens and closes the jaws repeatedly while the metal is hot. The microscopic wear at temperature establishes perfectly mated bearing surfaces, resulting in a joint with zero lateral play but frictionless rotational movement⁵³.
5. Finally, the jaws are heated and hammered closed directly around the specific piece of stock they are intended to hold, custom-molding the grip for absolute, unwavering security⁴⁷.

Part V: Thermomechanical Processing and Heat Treatment

Forging relies entirely on the thermal plasticity of steel, but the extreme heat cycles required for shaping severely degrade the internal crystalline structure of the metal⁵. Once the mechanical shaping of the tongs (or any forged tool) is complete, the steel must undergo precise thermomechanical processing to restore its mechanical properties⁵⁵.

Normalizing and Grain Refinement

When steel is heated to high forging temperatures (frequently exceeding $1000^{\circ}C$), the microscopic crystalline grains within the metal grow massively in size⁵⁴. A large, coarse grain structure equates directly to extreme brittleness and poor impact toughness⁵⁵. Furthermore,

uneven hammering induces massive internal stress differentials across the complex geometry of the tool⁵⁷.

To repair this damage, the tongs must be normalized. Normalization is a thermal cycling process that forces the steel to recrystallize, wiping out the massive forging grains and annihilating the stored strain energy⁵.

1. The steel is heated slowly and evenly until it reaches the point of decalescence. At approximately 724°C (depending heavily on carbon content), the steel undergoes a fundamental atomic phase shift from a body-centered cubic (bcc) ferrite/pearlite structure to a face-centered cubic (fcc) structure known as austenite⁵. During this atomic rearrangement, the steel absorbs thermal energy without increasing in physical temperature, casting a visible, moving shadow across the glowing metal (decalescence)⁵⁷.
2. Once fully austenitized (slightly above the critical, non-magnetic temperature), the steel is removed from the forge and allowed to cool exclusively in still, ambient air until it returns to room temperature (or turns completely black)⁵.
3. As it cools, it undergoes recalscence, transforming back to pearlite and nucleating entirely new, vastly smaller grains⁵.
4. This thermal cycle is typically repeated three times, at slightly descending peak temperatures, to iteratively refine the grain structure to a highly desirable microscopic level⁵⁵.

Tongs, typically fabricated from mild steel, do not require further heat treatment; normalization leaves them tough, resilient, and ready for a lifetime of service⁵⁹.

Quenching and Tempering High-Alloy Scrap (42CrMo4)

If the blacksmith is fabricating struck tooling (such as hardy cut-offs, punches, or small bench anvils) from the scavenged 42CrMo4 forklift tines, normalization must be followed by a rigorous quenching and tempering protocol¹².

The Quench: To achieve high hardness, the 42CrMo4 steel is austenitized between 840°C and 870°C ¹⁵. It must then be rapidly cooled (quenched) to bypass the formation of soft pearlite and force the carbon to remain trapped in a highly strained, supersaturated body-centered tetragonal (bct) crystal lattice known as martensite¹⁵.

Crucially, the chosen quench medium dictates the cooling rate and the severity of thermal shock. Due to the high hardenability provided by the chromium and molybdenum in 42CrMo4, water quenching is excessively severe¹⁵. The volumetric expansion of martensite coupled with the drastic thermal gradient of a water quench generates transient microscopic tensile stresses exceeding 800 MPa at the junctions of the martensitic laths⁶³. This massive internal stress easily exceeds the yield strength of the material, resulting in catastrophic quench cracking¹⁵. Therefore, 42CrMo4 and similar high-alloy steels must be quenched exclusively in engineered quenching oils. Oil provides a slower, controlled cooling curve that minimizes internal stress while still achieving full martensitic transformation (yielding an as-quenched

hardness of approximately 50–55 HRC)¹⁵.

The Temper: As-quenched martensite is glass-hard and totally unsuitable for kinetic impact¹⁵. If struck, it will shatter like glass. The steel must be immediately tempered—reheated to a sub-critical temperature to allow some trapped carbon to precipitate out, relieving internal stress and restoring necessary ductility¹⁵.

For 42CrMo4 tooling subjected to impact, a tempering temperature between 540°C and 680°C is required¹². A higher temper at 650°C will drop the hardness to a highly resilient 28–32 HRC, maximizing the material's impact toughness (absorbing over 35 Joules of impact energy via ISO-V notch testing) and rendering it virtually indestructible under the hammer¹².

Part VI: Occupational Health and Safety Protocols in the Forge

The manipulation of incandescent steel introduces acute industrial hazards. Adherence to occupational safety standards—such as those outlined by the German Social Accident Insurance (DGUV) and the Employer's Liability Insurance Association for the Energy, Textile, Electrical, and Media Products Sectors (BG ETEM)—is mandatory to mitigate catastrophic injury⁶⁷.

Inhalation and Chemical Hazards

Zinc Fume Fever: Under no circumstances should the blacksmith heat, cut, or forge galvanized steel (such as hardware store plumbing pipe or plated brackets). Galvanized steel is coated in a sacrificial layer of zinc. At temperatures exceeding 400°C , the zinc rapidly vaporizes and oxidizes upon contact with ambient air to form zinc oxide particulates⁷⁰. Inhalation of these sub-micron fumes causes acute zinc fume fever—a severe toxic reaction characterized by violent chills, nausea, a metallic taste, and high fever manifesting 4 to 10 hours after exposure⁷⁰. If a salvaged scrap piece is suspected of being plated, it must be completely avoided or chemically stripped in a cold acid bath prior to any thermal exposure.

Carbon Monoxide and Atmospheric Toxins: Solid-fuel forges burning coal or charcoal rely on deep, oxygen-starved fuel beds to create a reducing atmosphere⁴². The chemical byproduct of this incomplete combustion is carbon monoxide (CO)⁴². CO is an invisible, odorless gas that aggressively binds to hemoglobin, causing rapid asphyxiation. The operation of any solid-fuel or gas forge in an enclosed space is an extreme, lethal hazard. Workspaces must feature active, high-volume cross-ventilation or purpose-built industrial extraction hoods⁶⁹.

Respirable Crystalline Silica: The fabrication of traditional refractory linings utilizing clay, high-silica sand, or grog (crushed firebrick) introduces the risk of aerosolizing respirable crystalline silica⁷⁰. Prolonged inhalation of silica dust causes silicosis and is classified as a severe carcinogen. All mixing of dry refractory powders must be done as a "wet-work" process to bind the dust, and N95 or P100 particulate respirators must be worn during preparation⁷⁰.

Combustible Dust Explosions: The accumulation of fine metal dust or coal dust presents a

severe explosion hazard. Under the STOP principle (Substitution, Technical, Organizational, Personal) recommended for minimizing explosive risks, work areas must be regularly cleared of fine particulates, and dry sweeping must be replaced with wet-wiping or industrial vacuuming to prevent aerosolizing explosive dust clouds⁷¹.

Tool Safety, Heat Stress, and Kinetic Hazards

Heat Stress and Ergonomics: Forging adjacent to a radiant heat source frequently elevates

the ambient working temperature above $35^{\circ}C$, classifying the forge as a high-heat workplace (Hitze Arbeitsplatz) under DGUV Information 213-002⁷². The human body requires approximately 14 days to fully acclimatize to these conditions⁷². Without acclimatization, the risk of heat exhaustion and life-threatening heat stroke increases exponentially⁷². Operators must increase fluid intake well beyond the standard 2.5 liters per day and immediately cease work if symptoms of headache, nausea, or dizziness manifest⁷².

Kinetic Hazards and Acoustic Trauma: DGUV Information 209-001 strictly dictates the maintenance and proper application of hand tools in metalworking environments⁷³.

1. **Mushroomed Tooling:** Hammer faces, punches, and chisels must be routinely dressed to remove "mushrooming"—the localized flaring of metal at the striking end. Struck mushroomed metal can violently spall, ejecting shrapnel at bullet velocities⁷⁴.
2. **Structural Integrity:** The use of files or hardened rasps as makeshift struck tools is strictly prohibited. High-carbon tools that have not been tempered appropriately for impact will shatter explosively when struck by a hammer⁷⁴.
3. **Tongs:** Tongs must grip the workpiece with absolute, redundant security⁴⁷. Using incorrect jaw profiles, or substituting slip-joint pliers, guarantees that the workpiece will eventually slip under the kinetic impact of the hammer, launching glowing steel across the workspace⁴⁷.
4. **Acoustic Trauma:** The ringing of an undampened anvil routinely exceeds the 85 dB(A) threshold mandated for hearing protection⁷⁵. In addition to the mechanical dampening of the anvil utilizing silicone, operators must employ personal protective equipment (PPE) such as earmuffs or custom-molded earplugs to prevent irreversible noise-induced hearing loss⁷⁵.

Conclusion

The successful transition into the craft of blacksmithing is defined not by the purchase of pristine, expensive tooling, but by the intelligent, metallurgically sound adaptation of industrial scrap. By acknowledging the complex pearlitic microstructure of AREMA-grade railroad track and the deep-hardening Q+T mechanics of 42CrMo4 forklift tines, the novice can fabricate a massive, highly efficient starter anvil. Modifying this geometry to place columnar mass directly under the hammer, radiusing the edges to eliminate stress risers, and utilizing the acoustic impedance properties of silicone caulk to deaden vibration ensures maximum kinetic transfer and absolute occupational safety.

Furthermore, the sequential fabrication of the blacksmith's first pair of tongs—mastering the

90 -degree set-down, the isolation of the boss, and the structural superiority of the hot-punched rivet hole—provides the mechanical literacy required to forge all subsequent tooling. Coupled with a rigorous adherence to proper thermomechanical normalizing protocols and an uncompromising respect for respiratory, acoustic, and kinetic safety guidelines, the beginner establishes a foundation of metallurgical competence capable of enduring a lifetime at the anvil.

Works cited

1. What Grade of Steel Is Railroad Track? 1084, Carbon Content & Rail, <https://machininganswers.com/what-grade-of-steel-is-railroad-track/>
2. Railroad Track Steel: Properties & Material Guide - Glory Rail, <https://railroadtrackforsale.com/2025/12/17/railroad-track-steel-properties-material/>
3. Proceedings of - ROSA P, https://rosap.ntl.bts.gov/view/dot/35650/dot_35650_DS1.pdf
4. 2011-3.pdf - Materials Technology Group - University of Houston, <https://mt-group.egr.uh.edu/wp-content/uploads/2023/07/2011-3.pdf>
5. Normalizing - Metallurgy for Dummies, <https://www.metallurgyfordummies.com/normalizing.html>
6. Mechanical properties and wear performance of premium rail steels, https://www.researchgate.net/publication/223712679_Mechanical_properties_and_wear_performance_of_premium_rail_steels
7. Wear of conventional pearlitic and improved bainitic steels, https://www.researchgate.net/publication/248324795_Wear_of_conventional_pearlitic_and_improved_bainitic_steels
8. 4140 Forklift Tine Anvil & Introduction - I Forge Iron, <https://www.iforgeiron.com/topic/47509-4140-forklift-tine-anvil-introduction/>
9. Steel grade 42CrMo4 | moris.eu, <https://moris.eu/en/steel-grades/42CRMO4>
10. Stahlsorte - Wikipedia, <https://de.wikipedia.org/wiki/Stahlsorte>
11. Bedeutung der Stahlsortenbezeichnung für ausgewählte Stähle, <https://www.salzgitter-flachstahl.de/de/news/details/bedeutung-der-stahlsortenbezeichnung-fuer-ausgewaehlte-staehle-aus-dem-lieferprogramm-der-salzgitter-flachstahl-20784.html>
12. Overview of 42CrMo4 Steel: Properties and Applications, <https://ambhe.com/42crmo4-steel/>
13. S45C vs. 42CrMo4: A Comprehensive Comparison - Lion Metal, <https://www.shlionmetal.com/mold-steel/s45c-vs-42crmo4-a-comprehensive-comparison/>
14. EN19 / 42CrMo4 Steel – Properties, Hardness (HRC) & Composition, <https://niftyalloys.com/blogs/en19-42crmo4-alloy-steel>
15. Heat Treatment Guide for Alloy Steels, <https://tksteels.com/blog/blog-heat-treatment-alloy-steels.php>
16. What gives an anvil rebound? : r/Blacksmith - Reddit,

- https://www.reddit.com/r/Blacksmith/comments/lfwy7b/what_gives_an_anvil_rebound/
17. Blacksmith's Helper: How It Works, Diagram & Examples | FIRGELLI,
<https://www.firgelliauto.com/blogs/mechanisms/blacksmith-s-helper>
 18. Anvil stand mass and stiffness - I Forge Iron,
<https://www.iforgeiron.com/topic/67711-anvil-stand-mass-and-stiffness/>
 19. Professional Blacksmithing: Choosing an Anvil - Persimmon Forge,
<http://persimmonforge.blogspot.com/2011/11/choosing-anvil.html>
 20. Anvil weight question - Tools and Tool Making - Bladesmith's Forum,
<https://www.bladesmithsforum.com/index.php?/topic/35109-anvil-weight-question/>
 21. The physics of an anvil [closed],
<https://physics.stackexchange.com/questions/233424/the-physics-of-an-anvil>
 22. Railroad Track as stock? Not an Anvil? - I Forge Iron,
<https://www.iforgeiron.com/topic/35645-railroad-track-as-stock-not-an-anvil/>
 23. Railroad Track Anvil - which way to orient? - I Forge Iron,
<https://www.iforgeiron.com/topic/14131-railroad-track-anvil-which-way-to-orient/>
 24. Anvil rebound - Factual Questions - Straight Dope Message Board,
<https://boards.straightdope.com/t/anvil-rebound/993535>
 25. Vinegar or grinding to prep a railroad track anvil - I Forge Iron,
<https://www.iforgeiron.com/topic/59552-vinegar-or-grinding-to-prep-a-railroad-track-anvil/>
 26. Shop Anvil From Railroad Track : 7 Steps (with Pictures) - Instructables,
<https://www.instructables.com/Shaping-of-a-Railroad-Anvil>
 27. Making Aso / Railroad Track Anvil Using Angle Grinders.,
<https://www.instructables.com/Making-Aso-Railroad-Track-Anvil-Using-Angle-Grinder/>
 28. my train track anvil | Page 2 | The Garage Journal,
<https://www.garagejournal.com/forum/threads/my-train-track-anvil.245175/page-2>
 29. How do I prevent cracking like this? : r/Blacksmith - Reddit,
https://www.reddit.com/r/Blacksmith/comments/1niv0vl/how_do_i_prevent_cracking_like_this/
 30. What causes this? : r/Blacksmith - Reddit,
https://www.reddit.com/r/Blacksmith/comments/1aiu9sl/what_causes_this/
 31. Liquid Penetrant and Magnetic Particle Testing at Level 2,
<http://aec.gov.sy/ndt/pdf/specifications/IAEA-TECDOC-628/No11.pdf>
 32. M Eng | PDF | Soldering | Alloy - Scribd,
<https://www.scribd.com/document/508729535/M-eng>
 33. Jesenice Welding Electrode Catalog | PDF | Metallic Elements - Scribd,
<https://www.scribd.com/doc/216721726/Elektrode-Jesenice-Katalog>
 34. Catalog Lastek 05/11/01, <https://nst.no/dokumenter/produktinfo/LastekCatEng.pdf>
 35. WIA Austarc 16TC Welding Guide - Scribd,
<https://www.scribd.com/document/232061337/The-Australian-Welding-Guide-20>

36. Data Book Esab | PDF | Welding | Construction - Scribd,
<https://www.scribd.com/document/301551882/Data-Book-Esab>
37. Metrode Consumables PDF | PDF | Welding | Construction - Scribd,
<https://id.scribd.com/document/333718503/Metrode-Consumables-pdf>
38. (PDF) Weldability Assessment of Various Steels by Hard-Facing,
https://www.researchgate.net/publication/360172827_Weldability_Assessment_of_Various_Steels_by_Hard-Facing
39. (PDF) Theoretical-experimental estimation of weldability of different,
https://www.researchgate.net/publication/365762952_Theoretical-experimental_estimation_of_weldability_of_different_types_of_steels_by_hard_facing
40. Weldability Assessment of Various Steels by Hard-Facing - MDPI,
<https://www.mdpi.com/1996-1944/15/9/3082>
41. Structure and example solutions of conical picks a ... - ResearchGate,
https://www.researchgate.net/figure/Structure-and-example-solutions-of-conical-picks-a-structure-of-a-typical-pick-b_fig1_329419210
42. 2-DIY Traditional Blacksmith Forge Guide.pdf
43. Mechanical Vibrations and Noise Control - DOKUMEN.PUB,
<https://dokumen.pub/mechanical-vibrations-and-noise-control.html>
44. Steel Selection Based on European Standards - RoyMech,
https://www.roytech.co.uk/Useful_Tables/Matter/Steel_Europe.html
45. Design Acoustics: Gh. Reza Sinambari | PDF - Scribd,
<https://www.scribd.com/document/641961722/Untitled>
46. viscoelastic damping materials: Topics by Science.gov,
<https://www.science.gov/topicpages/v/viscoelastic+damping+materials>
47. Best Beginner Blacksmith Tongs 2026: 3 Picks - HobbyStack,
<https://hobbystack.net/tools/best-beginner-blacksmith-tongs>
48. Knife Makers Tongs - Beginners Place - Bladesmith's Forum Board,
<https://www.bladesmithsforum.com/index.php?topic/38482-knife-makers-tongs/>
49. A Progression of Tongs : r/Blacksmith - Reddit,
https://www.reddit.com/r/Blacksmith/comments/544mt0/a_progression_of_tongs/
50. Bolt Tongs Forged of 2 Railroad Spikes - Instructables,
<https://www.instructables.com/Bolt-tongs-from-2-railroad-spikes/>
51. First set of tongs, what am I missing - I Forge Iron,
<https://www.iframeiron.com/topic/50573-first-set-of-tongs-what-am-i-missing/>
52. First tongs progress! : r/Blacksmith - Reddit,
https://www.reddit.com/r/Blacksmith/comments/1utmyug/first_tongs_progress/
53. Making tongs - Beginners Place - Bladesmith's Forum Board,
<https://www.bladesmithsforum.com/index.php?topic/12252-making-tongs/>
54. Normalization - COUSTIL - Forge / Coutellerie / Bladesmithing - Free,
http://coustil.free.fr/metal_normal_gb.html
55. Normalizing - Beginners Place - Bladesmith's Forum Board,
<https://www.bladesmithsforum.com/index.php?topic/20607-normalizing/>
56. On Forging, Temperature, & Grain Size - Crossed Heart Forge,
<https://islandblacksmith.ca/2014/04/on-forging-temperature-grain-size/>

57. Normalization, Grain Refinement, Austenitizing, Tempering... Warps,
<https://knifedogs.com/threads/normalization-grain-refinement-austenitizing-tempering%E2%80%A6-warps-and-timing-questions.52373/>
58. Grain Refinement by Repeated Quenching : r/Blacksmith - Reddit,
https://www.reddit.com/r/Blacksmith/comments/5lipob/grain_refinement_by_repeated_quenching/
59. Normalising cycles are a blacksmith's best friend. : r/Blacksmith,
https://www.reddit.com/r/Blacksmith/comments/1mth15b/normalising_cycles_are_a_blacksmiths_best_friend/
60. (PDF) Analysis of tempering temperature and vegetable oil,
https://www.researchgate.net/publication/371050559_Analysis_of_tempering_temperature_and_vegetable_oil_quenchant_viscosity_effect_on_mechanical_properties_of_42CrMo4_steel
61. Quenching and Tempering Steel: Process & Benefits,
<https://prosteelsupply.com/quenching-and-tempering-steel-process/>
62. Hardening | Strength and Durability Through Heat Treatment - Camcut,
<https://www.camcut-group.com/en-us/support/machine-shop-glossary/hardening->
63. Water quenching cracking mechanism and prevention of steels,
<https://www.tandfonline.com/doi/pdf/10.1080/25787616.2023.2280352>
64. 42CrMo4 Steel: How to Unlock the Ultimate Performance?,
<https://www.round-bars.com/a-complete-analysis-of-the-heat-treatment-process-of-42crmo4-steel-how-to-unlock-its-ultimate-performance/>
65. 42CrMo4, 1.7225, 42CrMoS4, AISI 4140, 42CD4, 708M40 - alloy steel,
<https://virgamet.com/offer/40hm-42crmo4-1-7225-aisi-4140-toughening-steel>
66. Technical Datasheet QT-Steel 42CrMo(S)4 +QT +SH,
https://swisssteel-group.com/content-media/documents/_import/42CrMoS4_en.pdf
67. Gesetzliche Unfallversicherung - IHK,
<https://www.ihk.de/blueprint/servlet/resource/blob/5091122/134612a3d94c93b0d4f72b463945cd40/merkblatt-berufsgenossenschaft-stand-2020--data.pdf>
68. 3 Arbeitsplätze und Tätigkeiten: Gefährdungen und Maßnahmen,
https://www.bgbau-medien.de/handlungshilfen_gb/daten/dguv/109_607/3.htm
69. Hufbeschlagn/Hufbeschlagnschmiede - BGHM,
<https://www.bghm.de/arbeitsschuetzer/praxishilfen/handlungshilfen-fuer-klein-und-mittelbetriebe/hufbeschlagn>
- 70.
71. Explosions-Gefahr durch Metall-Staub - DGUV Arbeit & Gesundheit,
<https://aug.dguv.de/leichte-sprache/explosion-metall-staub/>
72. Hitzearbeitsplatz - WEKA Intelligence,
<https://www.weka.de/arbeitsschutz-gefahrstoffe/hitzearbeitsplatz/>
73. DGUV Regel 109-607: Branche Metallbau, 4 Anhang,
https://www.bgbau-medien.de/handlungshilfen_gb/daten/dguv/109_607/4.htm
74. Handwerkzeuge - BGHM,
<https://www.bghm.de/arbeitsschuetzer/themen/maschinen/handwerkzeuge>

75. Deutscher Betriebsärzte-Kongress 4. – 7. Oktober 2023 in Freiburg,
https://www.asu-arbeitsmedizin.com/sites/default/files/2026-01/vdbw_abstracts_2023.pdf